

General Environmental Incident Summary

Incident: 3655 **Date/Time Notice:** 2/14/2015 1122 **DEM Incident No:**
Responsible Party: Twin Eagle Transport
Date Incident: 2/14/2015 **Time Incident:** 10:57 **Duration:** 6 hours
County: McKenzie **Twp:** 152 **Rng:** 101 **Sec:** 18 **Qtr:**
Lat: 47.97984 **Long:** -103.66170 **Method:** Interpolation from map
Location Description: Location of the nearest intersection of the spill is 39th St.NW & State Hwy. 85

Submitted By: Teddy Young **Affiliation:** Client OSRO
Address: 131 Keating Dr.
City: Belle Chasse **State:** LA **Zip:** 70037

Received By:

Contact Person: Teddy Young
4867 Hwy 85 S
Williston, ND 58801

Distance Nearest Occupied Building: 500 Feet **Release Contained:** Yes

Type of Incident: Tanker Truck Overflow

Description of Released Contaminant: Crude Oil

Volume Spilled: 6.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Yes

Cause of Incident:

The Tanker Truck Operator left tank valve open while offloading crude oil. The crude oil leaked into a secondary containment getty box then overflowed onto the ground.

Risk Evaluation:

There was no immediate risk reported.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 05 - air and soil

Potential Environmental Impacts:

Impact to soil is a certainty. Remediation will occur if necessary.

Action Taken or Planned:

The Tanker Truck's OSRO responded to assess, clean-up, and re-mediate soil (if required).

Wastes Disposal Location: I currently do not have this information.

Agencies Involved: Local Emergency Manager, National Response Center

Updates

Date: 2/14/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Unloading leakage accident. Followup to determine potential impact area is necessary.

Date: 2/17/2015 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

15:10 The weather is clear, 10 °F with wind from the northwest at 20+ mph. The Twin Eagle loading area is located on the north side of 39th Street on the west side of Highway 85 near the Enbridge tanks. Scraping has been done around the gitty boxes on the north side of the loading facility. There is no staining of oil in the area of the boxes or oil standing. The area is currently frozen; some current melt water is frozen on south side of property. The contact on the report indicated that the spill was cleaned up the same day of incident. The site has a secondary dike system around the west and south sides of property. The south side of dike is along the road ditch. No further followup is needed at this time. 47 58.778; -103 39.826